



June 18, 2010

MR. JAN URBAHN
GENERAL MANAGER, SAFETY ENGINEERING
AND INTELLIGENT TRANSPORTATION SYSTEMS
BMW OF NORTH AMERICA, LLC
PO BOX 1227
WESTWOOD, NJ 07675-1227

NVS-215kjs 10V-273

SUBJECT: ROLL GEAR PIN MOUNTING ATTACHMENT

DEAR MR. URBAHN:

This letter serves to acknowledge BMW of North America, Inc.'s (BMW) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the vehicles listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/G 650 X US CHALLENGE/2007 BMW/G 650 X US COUNTRY/2007-2008 BMW/G 650 X US MOTO/2007

Mfg's Report Date: June 15, 2010 NHTSA Campaign Number: 10V-273

Components: POWER TRAIN

Potential Number of Units Affected: To be provided

Summary:

BMW IS RECALLING CERTAIN MODEL YEAR 2007 AND 2008 G 650 X COUNTRY, G 650 X CHALLENGE, AND G 650 X MOTO MOTORCYCLES MANUFACTURED FROM NOVEMBER 29, 2006 THROUGH MAY 19, 2008. OVER TIME, THE ROLL GEAR PIN'S MOUNTING ATTACHMENT COULD BREAK.

Consequence:

IF THIS OCCURS, IT WOULD BE POSSIBLE FOR FRAGMENTS OF THE ATTACHMENT TO BECOME TRAPPED BETWEEN THE DRIVE CHAIN AND THE REAR SPROCKET. THE REAR WHEEL COULD LOCK UP, POSSIBLY RESULTING IN A CRASH.

Remedy:

THE MANUFACTURER HAS NOT YET PROVIDED THE AGENCY WITH A REMEDY PLAN OR A NOTIFICATION SCHEDULE. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes:

OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available.

Please provide us with the quantity of vehicles involved for this recall.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division Office of Defects Investigation

Enforcement